


SD Card Interface

Zynq PS SDIO

SDIO MIO Settings in PS7 IP Configuration if external level shifter is used:

- speed (slew rate): slow
- pullup: disabled

 It is important to disable the pull-ups, otherwise some SD card may exhibit systematic or random problem at initialization.

Bank 0 I/O Voltage LVC MOS 3.3V Bank 1 I/O Voltage LVC MOS 1.8V

Search:

Peripheral	IO	Signal	IO Type	Speed	Pullup	Direction	Polarity
Memory Interfaces							
I/O Peripherals							
<input checked="" type="checkbox"/> ENET 0	MIO 16 .. 27						
<input type="checkbox"/> ENET 1							
<input checked="" type="checkbox"/> USB 0	MIO 28 .. 39						
<input type="checkbox"/> USB 1							
<input checked="" type="checkbox"/> SD 0	MIO 40 .. 45						
<input checked="" type="checkbox"/> CD	EMIO						
<input checked="" type="checkbox"/> WP	EMIO						
<input type="checkbox"/> Power							
SD 0	MIO 40	clk	LVC MOS 1.8V	slow	disabled	inout	
SD 0	MIO 41	cmd	LVC MOS 1.8V	slow	disabled	inout	
SD 0	MIO 42	data[0]	LVC MOS 1.8V	slow	disabled	inout	
SD 0	MIO 43	data[1]	LVC MOS 1.8V	slow	disabled	inout	
SD 0	MIO 44	data[2]	LVC MOS 1.8V	slow	disabled	inout	
SD 0	MIO 45	data[3]	LVC MOS 1.8V	slow	disabled	inout	


Example settings for SDIO MIO pins (TE0720), MIO pullups are disabled.

SDIO Peripheral Clock



This clock may as of Xilinx default sometimes be set to 125MHz, this would cause Xilinx FSBL to fail on clock lookup when setting SD clock to 400KHz. SDIO peripheral clock should be set to 100MHz or 50MHz.

Level shifter


Modules that expose SDIO Interface on the B2B Connector from 1.8V VCCIO bank need SD Level shifter IC on the baseboard.

 When using TXS02612 as SDIO level shifter external pullups should not be used on CMD and DAT lines.

TE0701 and TE0703 have pullup resistor on CMD line, which has been removed since:

Base	CMD pullup Resistor R43	Removed since
TE0701		TE0701-05 Serial number: TBD
TE0703		TE0703-04 Serial number: TBD

This extra pullup may cause problems in some special cases with some SD Cards. As example hama micro-SD Card when used with PS7 SDIO MIO pullups enabled and R43 loaded had sporadic initialization problems on TE0703, removing R43 solved the issue.

 Some other designs and boards that use TXS02612 may have pullup on CMD, this is incorrect as per TXS02612 datasheet. Xilinx ZC702 board that uses SDIO level shifter with similar technology has the CMD pullup in schematic with marking "DNP" do not populate.

When using SDIO level shifter from other vendors, or other level shifting technology then requirements listed in the vendor datasheet and application notes should be followed.

References

- [TXS02612 Documentation from TI](#)
- [ZC702 Documentation from Xilinx](#)