

PCN-20171110 TE0600-03 SPI Flash Change

[Download PDF version of this document.](#)

Company	Trenz Electronic GmbH
PCN Number	PCN-20171110
Title	TE0600-03 SPI Flash change
Subject	BOM change
Issue Date	20171110

Products Affected

This change affects all Trenz Electronic TE0600 SoMs of the third revision: TE0600-03-*.

Affected product
TE0600-03-*

Changes

#1 Change SPI Flash from W25Q128FVEIG to W25Q128JVEIQ

Type: BOM change

Reason: W25Q128FV became obsolete

Impact: None

Method of Identification

All serial numbers larger 499957 are assembled with W25Q128JVEIQ.

Further the following serials are also assembled with W25Q128JVEIQ:

Serial	Article
499797	TE0600-03IN
499845	TE0600-03I
499850 - 499862	TE0600-03I
499869 - 499879	TE0600-03I
499887 - 499890	TE0600-03I
499892 - 499896	TE0600-03I

499898	TE0600-03I
499905 - 499906	TE0600-03I
499908 - 499926	TE0600-03I
499928, 499930, 499931	TE0600-03I
499933 - 499937	TE0600-03I
499939 - 499943	TE0600-03I
499945, 499948, 499949	TE0600-03I
499952, 499957	TE0600-03I

Production Shipment Schedule

From November 2017, after stock is gone.

Contact Information

If you have any questions related to this PCN, please contact Trenz Electronic's Technical Support at

- forum.trenz-electronic.de
- wiki.trenz-electronic.de
- support@trenz-electronic.de (subject = PCN-20171110)
- phone
 - national calls: 05223 65301-0
 - international calls: 0049 5223 65301-0

Disclaimer

Any projected dates in this PCN are based on the most current product information at the time this PCN is being issued, but they may change due to unforeseen circumstances. For the latest schedule and any other information, please contact your local Trenz Electronic sales office, technical support or local distributor.