

PCN-20230124 TEI0004-02 MEMS oscillator change

[Download PDF version of this document.](#)

Company	Trenz Electronic GmbH
PCN Number	PCN-20230124
Title	TEI0004-02 MEMS oscillator change
Subject	BOM change
Issue Date	2023-02-22

Products Affected

This change affects all Trenz Electronic TEI0004 SoMs: TEI0004-02*.

Affected Product
TEI0004-02

Change

#1 Changed MEMS oscillator (U7) from DSC6011ME2A-012.0000T to DSC6011ME2B-012.0000T.


Type: BOM change

Reason: EOL of component.

Impact: None.

Method of Identification

The change above is applied to boards with serial number greater than A26733 or 512242. The revision number is printed on the top side of the PCB and the serial number is glued on the FTDI chip.



Production Shipment Schedule

From now on, after old stock is gone. If the new revision is not suitable for your application and still the former revision of the board is needed, please contact us.

Contact Information

If you have any questions related to this PCN, please contact Trenz Electronics Technical Support at

- forum.trenz-electronic.de
- wiki.trenz-electronic.de
- support@trenz-electronic.de (subject = PCN-20230124)
- phone
 - national calls: 05741 3200-0
 - international calls: 0049 5741 3200-0

Disclaimer

Any projected dates in this PCN are based on the most current product information at the time this PCN is being issued, but they may change due to unforeseen circumstances. For the latest schedule and any other information, please contact your local Trenz Electronic sales office, technical support or local distributor.

This PCN follows JEDEC Standard J-STD-046.