

PCN-20230130 TEM0001-01A Components Change

[Download PDF version of this document.](#)

Company	Trenz Electronic GmbH
PCN Number	PCN-20230130
Title	TEM0001-01A Components Change
Subject	Components Change
Issue Date	2023-02-22

Products Affected

This change affects all Trenz Electronic TEM0001 SoMs: TEM0001-01A*.

Affected Product	Replacement
TEM0001-01A-010C	TEM0001-01A-ABC-2

Changes

#1 Changed SPI Flash (U1) from W74M64FVSSIQ to W25Q64JVSSIQ.

Type: BOM change
Reason: EOL of Component.
Impact: Secure authentication is not more available but frequency range is increased.

#2 Changed MEMS oscillator (U7) from DSC6011ME2A-012.0000T to DSC6011ME2B-012.0000T.

Type: BOM change
Reason: EOL of component.
Impact: None.

Method of Identification

Changes above are applied to boards with serial number greater than A29125 or 510476.

Production Shipment Schedule

From september 2023, after old stock is gone. If the new revision is not suitable for your application and still the former revision of the board is needed, please contact us.

Contact Information

If you have any questions related to this PCN, please contact Trenz Electronics Technical Support at

- forum.trenz-electronic.de
- wiki.trenz-electronic.de
- support@trenz-electronic.de (subject = PCN-20230130)
- phone
 - national calls: 05741 3200-0
 - international calls: 0049 5741 3200-0

Disclaimer

Any projected dates in this PCN are based on the most current product information at the time this PCN is being issued, but they may change due to unforeseen circumstances. For the latest schedule and any other information, please contact your local Trenz Electronic sales office, technical support or local distributor.

This PCN follows JEDEC Standard J-STD-046.