

PCN-20240208 TEF0008-02 Scope of Delivery change

[Download PDF version of this document.](#)

Company	Trenz Electronic GmbH
PCN Number	PCN-20240208
Title	TEF0008-02 Scope of Delivery change
Subject	BOM Change
Issue Date	2024-02-13

Products Affected

This change affects all Trenz Electronic TEF0008-02 with a serial number greater than 844880.

Changes

#1 Removed PCIe slot cover and screws from BOM.

Type: BOM Change

Reason: BOM Optimization.

Impact: PCIe slot cover and screws no longer available within product. If needed, PCIe slot cover and screws need to be ordered separately (Trenz article number 34034).

Method of Identification

The model code and revision number (TEF0008-02) are printed on the bottom side of the PCB. The serial number is written at the QR-code on the bottom side label.

Production Shipment Schedule

With immediate effect this change takes place. For further help please contact us.

Contact Information

If you have any questions related to this PCN, please contact Trenz Electronics Technical Support at

- forum.trenz-electronic.de
- wiki.trenz-electronic.de
- support@trenz-electronic.de (subject = PCN-20240208)
- phone
 - national calls: 05741 3200-0
 - international calls: 0049 5741 3200-0

Disclaimer

Any projected dates in this PCN are based on the most current product information at the time this PCN is being issued, but they may change due to unforeseen circumstances. For the latest schedule and any other information, please contact your local Trenz Electronic sales office, technical support or local distributor.

This PCN follows JEDEC Standard J-STD-046.