

PCN-20200818 KK0807-02 to KK0807-02A Hardware Revision Change

[Download PDF version of this document.](#)

Company	Trenz Electronic GmbH
PCN Number	PCN-20200818
Title	KK0807-02 to KK0807-02A Hardware Revision Change
Subject	Hardware Revision Change
Issue Date	2020-10-02

Products Affected

This change affects all KK0807-02:

Affected Product	Replacement
KK0807-02	KK0807-02A

Changes

#1 Added four M3 mountig holes.


Type: Hardware change

Reason: Request for screwed mounting of cooler on heatspreader.

Impact: The heatspreader is compatible with cooler KK0001-01.

Method of Identification

Models with 4 additional threads are revision 02A.



Production Shipment Schedule

The new revision 02A is available from September 2020, after old Stock is gone. If you still need revision 02 please contact us.

Contact Information

If you have any questions related to this PCN, please contact Trenz Electronics Technical Support at

- forum.trenz-electronic.de
- wiki.trenz-electronic.de
- support@trenz-electronic.de (subject = PCN-20200818)
- phone
 - national calls: 05741 3200-0
 - international calls: 0049 5741 3200-0

Disclaimer

Any projected dates in this PCN are based on the most current product information at the time this PCN is being issued, but they may change due to unforeseen circumstances. For the latest schedule and any other information, please contact your local Trenz Electronic sales office, technical support or local distributor.

This PCN follows JEDEC Standard J-STD-046.