

PCN-20190521 TE0715-04 Level Translator Change

[Download PDF version of this document.](#)

Company	Trenz Electronic GmbH
PCN Number	PCN-20190521
Title	TE0715-04 Level Translator Change
Subject	Level Translator Change
Issue Date	2019-05-24

Products Affected

This change affects all Trenz Electronic TE0715-04 SoMs: TE0715-04-*

Changes

#1 Replaced Leveltranslator LFXLA101L6X (U21) by FXLH1T45L6X

Type: BOM Change

Reason: Old Levelshifter was permanetly disabled.

Impact: Ethernet PHY LED0 signal translated and usable by FPGA

Method of Identification

Production serial numbers from 568440 and greater are assembled with the new Levelshifter.

Production Shipment Schedule

From Mai 2019, after old stock is gone.

Contact Information

If you have any questions related to this PCN, please contact Trenz Electronics Technical Support at

- forum.trenz-electronic.de
- wiki.trenz-electronic.de
- support@trenz-electronic.de (subject = PCN-20190521)
- phone
 - national calls: 05223 65301-0
 - international calls: 0049 5223 65301-0

Disclaimer

Any projected dates in this PCN are based on the most current product information at the time this PCN is being issued, but they may change due to unforeseen circumstances. For the latest schedule and any other information, please contact your local Trenz Electronic sales office, technical support or local distributor.