PCN-20201012 KK0808-03 to KK0808-05 Hardware Revision Change

Download PDF version of this document.

Company	Trenz Electronic GmbH
PCN Number	PCN-20201012
Title	KK0808-03 to KK0808-05 Hardware Revision Change
Subject	Hardware Revision Change
Issue Date	2020-10-28

Products Affected

This change affects KK0808-03:

Affected Product	Replacement
KK0808-03	KK0808-05

Changes

#1 Changed milled height profile.

Type: Hardware change

Reason: Revsion 05 of TE0808 has different skyline and is therefore mechanical not compatible with KK0808-03.

Impact: New heat spreader is compatible with TE0808-05, but not backwards compatible to older versions of TE0808.

#2 Added two more M3 mountig holes.


Type: Hardware change

Reason: Make compatible to an aktive cooler of the shelf.

 $\textbf{Impact:} \ \textbf{The Heatspreader is compatible with SZ05L from RADIAN HEATSINKS}.$

Method of Identification

Models with 2 additional threads are revision 05.



Production Shipment Schedule

Revision 05 is available from December 2020.

Contact Information

If you have any questions related to this PCN, please contact Trenz Electronics Technical Support at

- forum.trenz-electronic.de
- wiki.trenz-electronic.de
- support%trenz-electronic.de (subject = PCN-20201012)
- phone

 - national calls: 05741 3200-0
 international calls: 0049 5741 3200-0

Disclaimer

Any projected dates in this PCN are based on the most current product information at the time this PCN is being issued, but they may change due to unforeseen circumstances. For the latest schedule and any other information, please contact your local Trenz Electronic sales office, technical support or local distributor.

This PCN follows JEDEC Standard J-STD-046.