

PCN-20210326 TEC0053-04 TVS Diode

[Download PDF version of this document.](#)

Company	Trenz Electronic GmbH
PCN Number	PCN-20210326
Title	TEC0053-04 TVS Diode
Subject	BOM change
Issue Date	2021-04-08

Products Affected

This change affects TEC0053 of Revision 04: TEC0053-04.

Changes

#1 Change D6: LNBTVS6-221S to LNBTVS4-222S

Type: BOM change

Reason: Former diodes are Obsolete.

Impact: None.

Method of Identification

Boards with Serial number greater than 673885 (white QR Sticker) will have the new Diodes installed.

Production Shipment Schedule

Boards and assemblies produced after August 2021 have the replaced parts installed.

Contact Information

If you have any questions related to this PCN, please contact Trenz Electronics Technical Support at

- forum.trenz-electronic.de
- wiki.trenz-electronic.de
- support@trenz-electronic.de (subject = PCN-20210326)
- phone
 - national calls: 05741 3200-0
 - international calls: 0049 5741 3200-0

Disclaimer

Any projected dates in this PCN are based on the most current product information at the time this PCN is being issued, but they may change due to unforeseen circumstances. For the latest schedule and any other information, please contact your local Trenz Electronic sales office, technical support or local distributor.

This PCN follows JEDEC Standard J-STD-046.