PCN-20220610 TE0890-01 HyperRAM Change

Download PDF version of this document.

| Company | Trenz Electronic GmbH |
|------------|---------------------------|
| PCN Number | PCN-20220610 |
| Title | TE0890-01 HyperRAM Change |
| Subject | BOM change |
| Issue Date | 2023-06-26 |

Products Affected

This change affects all Trenz Electronic TE0890-01-P1C-5-A boards with serial numbers greater than 703626.

| Affected Products |
|-------------------|
| TE0890-01-P1C-5-A |

Changes

#1 Change HyperRAM (U2) from IS66WVH8M8BLL-100B1LI to IS66WVH8M8DBLL-100B1LI


Type: BOM change

Reason: HyperRAM improvement.


Impact: None.

Method of Identification

The serial number is written on a white QR code sticker and placed on the bottom side of the PCB within the white frame. The model code and revision number (TE0890-01) are printed on the top side of the PCB.







Production Shipment Schedule

With immediate effect the new variant is shipped. If the new revision is not suitable for your application and still the former revision of the board is needed, please contact us.

Contact Information

If you have any questions related to this PCN, please contact Trenz Electronics Technical Support at

- forum.trenz-electronic.de
- wiki.trenz-electronic.de
- support%trenz-electronic.de (subject = PCN-20220610)
- phone
 - o national calls: 05741 3200-0
 - o international calls: 0049 5741 3200-0

Disclaimer

Any projected dates in this PCN are based on the most current product information at the time this PCN is being issued, but they may change due to unforeseen circumstances. For the latest schedule and any other information, please contact your local Trenz Electronic sales office, technical support or local distributor.

This PCN follows JEDEC Standard J-STD-046.