

Hardware Revisions

Article Number	Remarks
TE0728-01-1AQF	Initial non public version, not fully automotive Industrial 4 GBit DDR3 IM4G16D3EABG-125I Industrial MAC address chips used
TE0728-02-1Q	Fully automotive Automotive NT5CB256M16CP-DIH 4 GBit DDR Removed industrial MAC chips, added automotive I2C EEPROM Added delay in reset circuit
TE0728-03-1Q	Removed functional safety chip Added 3.3V regulator serial numbers 455431 - 455431, 455440 and all numbers greater 457980 will have following additional changes: • U11 changed to 24LC64T-E/OT (rework of older boards recommended) • R46, R50, R51 and R54 assembled
TE0728-04-1Q	Updated Samtec connector footprint for better production yield.