

# PCN-20180524 TEF1001-01 microModule® DC/DC regulators Change

[Download PDF version of this document.](#)

<b>Company</b>	Trenz Electronic GmbH
<b>PCN Number</b>	PCN-20180524
<b>Title</b>	PCN-20180524 TEF1001-01 Module® DC/DC regulators Change
<b>Subject</b>	Module® DC/DC regulators change due to obsolescence
<b>Issue Date</b>	20180524

## Products Affected

This change affects only TEF1001-01

affected product	suggested upgrade
TEF1001-01	TEF1001-01A

## Changes

### #1 Module® DC/DC regulators change from LTM4676EY#PBF to LTM4676AEY#PBF

**Type:** BOM change

**Reason:** LTM4676EY#PBF became obsolete

**Impact:** none to this product. The manufacturer added some improvements. For more info see <http://www.analog.com/media/en/technical-documentation/product-information/4676amg.pdf>

## Method of Identification

Modules produced after Feb 2018 with serial numbers larger 510565 are assembled with LTM4676AEY#PBF.

## Production Shipment Schedule

After Feb 2018.

## Contact Information

If you have any questions related to this PCN, please contact Trenz Electronic's Technical Support at

- [forum.trenz-electronic.de](http://forum.trenz-electronic.de)
- [wiki.trenz-electronic.de](http://wiki.trenz-electronic.de)
- [support@trenz-electronic.de](mailto:support@trenz-electronic.de) (subject = PCN-20180524)
- phone
  - national calls: 05223 65301-0
  - international calls: 0049 5223 65301-0

## Disclaimer

Any projected dates in this PCN are based on the most current product information at the time this PCN is being issued, but they may change due to unforeseen circumstances. For the latest schedule and any other information, please contact your local Trenz Electronic sales office, technical support or local distributor.